



| | | | T | T | |
|---------------------|--|-----------------------------|---|---|--|
| | DOBLO CARGO | | | | |
| | 1.6 Multijet II | | | | |
| Vehicle model | | | | | |
| | | | | | |
| | - | | | | |
| Year | (09/2016>) | | | | |
| Engine Type | 263A8000 (Euro 6) 940C1000 (Euro 6) | | | | |
| CV(kW) @ rpm | 105 (77) @ 4.000 120 (88) @ 4.000 | | | | |
| N. of cylinders/cm3 | 4 / 1.598 | | | | |
| V-14- | | 10 | | | |
| Volts | 12 | | | | |
| Air Conditioning | Only Vehicles without A/C Suction Discharge | | | | |
| Recommended | | Discharge n | | | |
| fittings | | | | | |
| Compressors type | TM 13 / 15 QP 13 / 15 UP-UPF 150 SD5H14 / SD7H15 | | | | |
| Comments | - "E"=TM / QUE / UNICLA; "S"=SANDEN | | | | |
| | - "S" only for SD7H15 - For SD5H14 and SD7H15 Ø119 | | | | |
| | only Poly-V 7K-8K - Can be fit in right hand drive | | | | |
| | vehicles - It?s possible to mount the kit on vehicles with AC, although the AC | | | | |
| | compressor will have to be removed. | | | | |
| | In order to use SSMK 1183000415, the vehicle must be equipped from | | | | |
| | the vehicle must be equipped from factory with Conversion interface Box" 081 option (connector 15 ways | | | | |
| Clutch type | COMMInd at) clutch pulley | With clutch pulley | | | |
| | Poly-V Ø 119 5.546 rpm | Poly-V 6K Ø142 4.647 rpm | | | |
| | 3.540 ιμπ | 4.047 Ipili | | | |
| Kit No. | KC16090413 | KC16090413E/S | | | |
| Last update | 2016-09-30 | | | | |
| | | | | 1 | |

Date: 2024-01-11 Page 1